

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L3	6093	((fasten\$4 screw nut bolt rivet) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L4	102601	((stress strain load force pressure) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L5	1389	3 and 4	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:11
L6	50152	((stress strain load force tension) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L7	980	3 and 6	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L8	49	7 and ((thermo\$9 temperature) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:16
L9	1	"4550255".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
L10	1	"4806292".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
S1	3985	((two "2" second pair double couple) near3 plate) near4 (fasten\$4 screw nut bolt rivet)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:05
S2	346	S1 and seal\$4.clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:06
S3	0	S2 and 73/761.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:33

S4	15	S2 and ((stress strain load force pressure temperature) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:11
S5	15	S2 and ((stress strain load force pressure tension temperature) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:09
S6	2	S4 and tension	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:13
S7	2	S4 and tension.clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:08
S8	0	S6 and temperature	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:14
S9	9	S5 and temperature	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:14
S10	75	S1 and ((stress strain load force pressure tension temperature) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:33
S11	4	S1 and 73/761.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:34
S12	1	"4294122".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:36
S13	1	"4899591".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:19
S14	1	"5386733".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:38
S15	1	"5388463".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:38

S16	1	"5392654".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:38
S17	1	"5437525".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:40
S18	1	"5461923".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:41
S19	1	"5691815".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:41
S20	1	"5721380".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:41
S21	1	"5721380".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:42
S22	1	"6009759".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:42
S23	1	"4899591".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:42
S24	2	"2287950".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:16
S25	2	"2379800".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:16
S26	2	"2503141".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:17
S27	2	"2600029".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:17

S28	52	("3201977" "3306100" "3307393" "3308476" "3541844" "3650016" "3759090" "3810385" "3812709" "3812758" "3822587" "3823639" "3908508" "3918294" "3924444" "3930405" "3943819" "3969810" "3969960" "3975948" "3987668" "4014208" "4015464" "4062227" "4117731" "4121467" "4127788" "4144428" "4294122" "4339683" "4344216" "4363242" "4402222" "4413518" "4423634" "4445360" "4471657" "4565940" "4567766" "4569229" "4584676" "4601207" "4602511" "4633122" "4676109" "4760740").pn.	USPAT; USOCR	OR	OFF	2005/06/16 14:25
S29	14	S28 and temperature	USPAT; USOCR	OR	OFF	2005/06/16 14:25

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4	((("4,483,449") or ("4,845,470")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/17 10:22
L2	2	("6761073").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/17 10:45
L3	12205	heat\$5 near4 (second upper higher another) near3 (temperature).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 10:55
L4	4	3 and fastener near3 (tension load force stress strain).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 10:50
L5	8	3 and (screw rivet bolt nut fastener) near3 (tension load force stress strain).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 10:52
L6	98	heat\$3 near4 (second upper higher another) near3 (temperature) near6 (screw rivet bolt nut fastener)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 10:59
L7	27	6 and seal\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 10:59
L8	41	6 and (adhes\$4 seal\$3 glue)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 11:00

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L3	6093	((fasten\$4 screw nut bolt rivet) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L4	102601	((stress strain load force pressure) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L5	1389	3 and 4	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:11
L6	50152	((stress strain load force tension) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L7	980	3 and 6	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L8	49	7 and ((thermo\$9 temperature) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:16
L9	1	"4550255".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
L10	1	"4806292".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
L11	11726	heat\$5 near4 (second upper higher another) near3 (temperature).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:07
L12	2	11 and fastener near3 (tension load force stress strain).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:06
L13	46	heat\$5 near4 (second upper higher another) near3 (temperature) near6 (screw rivet bolt nut fastener)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:07

L14	15	13 and seal\$3	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:07
L15	25	13 and (adhesi\$4 seal\$3 glue)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:08